



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
**Date:** August 3, 2009

Reviewed: LAH

<b>Mine Name:</b> Diamond Mountain Resources	<b>Permit Number:</b> M/047/0066
<b>Operator Name:</b> Deseret Generation & Transmission	<b>Inspection Date:</b> July 29, 2009
<b>Inspector(s):</b> L Heppler	<b>Time:</b> 11:00 am
<b>Other Participants:</b> none	<b>Mine Status:</b> ACT

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Bond Renewal Date:** 11-29-2008 **Bond Amount:** \$275,000 **Permit fee** is up to date

**Purpose of Inspection:** Routine annual Inspection. This site was inspected as a large mine site on 09/07/2008

**Inspection Summary:** Mine disturbance is limited. No concurrent reclamation has been started but area is tight around the operation. Photos were taken to document site conditions.

**Conclusions and Recommendations:** Bond amount is past due for escalation. Due to last years depressed construction market, Escalation rate for 2009 is at a historic low (1.3%), Escalation letter will follow. OGM to continue annual inspections and monitor the site when in the area.

**Inspector's Signature**

LAH:vs

cc: Larry Jorgensen

NFS - daherron@fs.fed.us

O:\M047-Utah\M0470066-DG&T\inspections\lnsp-07292009.doc

